Oil Field Environmental Incident Summary

Responsible Party: Encore Energy Partners Operating LLC

Well Operator: ENCORE ENERGY PARTNERS OPERATING LLC

Well Name: CEYNAR 1

Field Name: BUFFALO WALLOW Well File #: 9852

Date Incident: 1/28/2014 Time Incident: 07:30 Facility ID Number:

County: MCKENZIE Twp: 148 Rng: 100 Sec: 8 Qtr: SE SW

Location Description: Flow line leak from the well head to the facility location. Release occurred by

the well head. Estimated 1 barrel got off well site and flowed to cultivated field. Cleanup crew will be able to scoop up oil, due to frozen ground. Farmer

has been notified.

Submitted By: Bart Brinkerhoff Received By:

Contact Person: Bart Brinkerhoff

Box 569

Powell, wy 82435

General Land Use: Cultivated Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MilesDistance Nearest Water Well:1 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

North and the Enter the				responded to rinter the		
	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	barrels	4.7	barrels	4.7	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: Written Report Received: 11/25/2014 Clean Up Concluded: 1/28/2014

Risk Evaluation:

no immediate risks.

Areal Extent:

One barrel of crude oil offsite of well head. Frigid temperatures, it can be scooped up.

Potential Environmental Impacts:

Will be cleaned up. No risks.

Action Taken or Planned:

Well was shut down. Cleanup crews have commenced.

Wastes Disposal Location: Oil will be vacuumed up. Fresh water rinse and oil will be recycled at

well facility.

Agencies Involved:

Updates

Date: 1/28/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from pipeline leak on location, near wellhead, partly ran off location. Followup is necessary to confirm cleanup of the agricultural field into which the estimated 1 bbl of oil ran.

Date: 2/13/2014 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/13/2014 at 16:41, on location. From north edge of the wellpad, ~30 ft wide~400 ft long path of ground has been scraped to cultivated field. No stains visible on vegetation around wellpad, on sides of scraped path, or in field stubble. Some piles of earth are still in path; left call with report contact to see when they will be removed.

Date: 2/14/2014 Status: Correspondence Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call with report contact. Earth piles may have impacted material; they will be removed by cleanup crew once weather improves.

Date: 8/27/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

8/27/2015 at 15:10, on location. Scraped area is revegetated, and earth piles have been removed. No visible staining in path. No further followup required.